

**To:** Enders, Jhana[Enders.Jhana@epa.gov]  
**From:** Pratt, David  
**Sent:** Mon 8/17/2015 9:03:46 PM  
**Subject:** RE: EPA Report for Surface Water and Sediment Sampling - Team 2

Yes

**From:** Enders, Jhana  
**Sent:** Monday, August 17, 2015 3:02 PM  
**To:** Pratt, David  
**Subject:** Re: EPA Report for Surface Water and Sediment Sampling - Team 2

so the horseshoe pond and the pond connected to it r both full?

Sent from my iPhone

On Aug 17, 2015, at 2:31 PM, Pratt, David <[Pratt.David@epa.gov](mailto:Pratt.David@epa.gov)> wrote:

Jhana,

Site conditions were essentially the same as yesterday. The only real issue encountered was that the new water sampler was skimming the water surface when collecting the samples. The issue was addressed and fixed onsite.

Also, I noticed the two holding ponds at the water treatment plant are full now. I did not encounter any citizens during the site visits.

David

**From:** Enders, Jhana  
**Sent:** Sunday, August 16, 2015 3:47 PM  
**To:** Pratt, David  
**Subject:** Re: EPA Report for Surface Water and Sediment Sampling - Team 2

Great! Thanks David.

Sent from my iPhone

On Aug 16, 2015, at 2:42 PM, Pratt, David <[Pratt.David@epa.gov](mailto:Pratt.David@epa.gov)> wrote:

Report attached....

David

<Gold King Mine SpillAugust16.docx>